

Rough Terrain Scissor Risk and Hazard Management

Models	GS2668DC	Safe	567	Maximum	7.92	Maximum	9.92
	GS2669DC	Working	680	Platform	7.70	Working	9.70
	GS2669BE	Load (kg)	680	Height (m)	7.70	Height (m)	9.70
	GS3268DC		454		9.75		11.75
	GS3369DC		454		9.75		11.75
	GS3369BE		454		9.75		11.75
	GS2668RT		567		7.92		9.92
	GS2669RT		680		7.92		9.92
	GS3268RT		454		9.75		11.75
	GS3369RT		454		9.75		11.75
	GS3384RT		1134		10.06		12.06
	GS4069DC		363		12.12		14.12
	GS4069BE		363		12.12		14.12
	GS4069RT		363		12.12		14.12
	GS4390RT		680		13.11		15.11
	GS5390RT		680		16.15		18.15

Contents

Introduction/Scope	1
Hazard Type Checklist	2
Hazard Control Measures	4
Product Safety	8

Introduction/Scope

In accordance with the relevant Occupational Health and Safety Legislation for the region you are working in (reference to state legislation is listed below), this report serves as confirmation that each model type Genie scissor, referenced above, has undergone a risk assessment and conforms to the applicable market standard (i.e. AS 1418.10). This risk assessment investigates the potential hazards associated with operation, maintenance, servicing, inspection, transportation and storage of the above referenced plants.

Our aim is to help ensure people at work (and any other personnel) are protected against health and safety risks associated with the use of the plant detailed within this report. Possible hazards and risks are to be assessed with respect to the use of the plant, on any jobsite, and control measures need to be incorporated, prior to the plants use, to maximise safety. For each identified risk, the designed control measures have been implemented to reduce these risks as far as practicable. Any residual risks, and their required control measures, can be found on the plant safety decals and in the operators, service and safety manuals.



Each model type receives a Certificate of Test and Compliance, through a third party consulting firm, that confirms the conformity to the applicable standard. Both of these documents can be provided to the owner/user at their request.

In accordance with the listed legislation, the information required to be supplied to the Purchaser, or User, of the plant by the designer, manufacturer, supplier and importer can be found in the operators and service manuals.

The listed legislation provides information, for employees, employers, plant installers etc., regarding providing a safe working environment. To assist in this effort, Genie also provides both operators and service manuals for their products which provides information regarding residual risks and their control measures. In addition to these manuals there may be industry safe use standards for the products that can also be used to help with identifying potential hazards on the jobsite (e.g. AS 2550.10).

Hazard Type Checklist

The table below provides a summary of some potential hazards associated with the use of the plant. Genie evaluates each of these potential hazards during the risk assessment process in an effort to select specific control measures, (e.g. designs, guarding, warnings) that will reduce the likelihood that the operator, platform occupants, maintenance personnel or bystanders will be exposed to the hazard. Many of these hazards can be identified in the relevant States Plant Hazard Guidance document, and AS1418.10 Appendix A, which is the governing design standard for these plant.

Table 1					
Hazard Type Checklist					
CRUSHING, ENTANGLEMENT, CUTTING, SEVERING, STABBING, PUNCTURING, SHEARING, FRICTION, IMPACT, TRAPPING	 Can anyone's hair, clothing, gloves, cleaning apparatus or any other materials become entangled in moving parts, or objects in motion. Can anyone be crushed due to: material falling from plant uncontrolled motion or unexpected movement of plant the plant tipping or rolling over inadequate slowing or stopping devices of plant to control movement support structure collapse being thrown from or under the plant coming in contact with moving parts of the plant during testing, inspection, operation, maintenance, cleaning or repair being trapped between the plant and materials or fixed structures Cutting, stabbing & puncturing due to: contact with sharp or flying objects coming in contact with moving parts of the plant during testing, inspection, operation, maintenance, cleaning or repair being trapped between the plant and materials or fixed structures Cutting, stabbing & puncturing due to: contact with sharp or flying objects coming in contact with moving parts of the plant during testing, inspection, operation, maintenance, cleaning or repair of the plant parts of plant or worksite material disintegrating or falling movement of plant can anyone's body parts be sheared between moving parts or surfaces of the plant 				
	 can anyone be burnt due to contact with moving parts or surfaces of the plant can anyone be struck by moving objects due to uncontrolled or unexpected movement of plant or work pieces (i.e. failure of the control system) 				
	 Can anyone be injured due to: 				
ERGONOMIC,	 uneven or slippery work surfaces 				
SLIPPING,	 poor housekeeping in the vicinity of or in the plant 				
TRIPPING,	 obstacles being placed in the vicinity of the plant 				
FALLING	o due to repetitive body movements				
	 constrained body posture or the need for excessive effort 				



 design inefficiency causing mental or psychological stress
 inadequate or poorly placed lighting of plant or workers IN THE WORKING AREA
 lack of failsafe measures against human error or human behaviour
 mismatch of plant with natural human limitations
 unhealthy posture or excessive efforts
 lack of personal fall protective equipment
 inadequate design/positioning of controls

	Table 1				
Hazard Type Checklist					
HIGH PRESSURE FLUIDS, HIGH TEMPERATURES, FIRE/EXPLOSION	 Can anyone come into contact with fluids under high pressure, due to plant failure or misuse Can anyone come into contact with objects at high temperatures, or objects which can cause fire or burning Can anyone suffer illness due to exposure to high or low temperatures Can anyone be injured by explosion of gases, vapours, liquids, dusts or other substances triggered by the operation of the plant or material handled by the plant 				
SUFFOCATION	 Can anyone be suffocated due to lack of oxygen, or atmospheric contamination 				
ELECTRICAL	 Can anyone be injured by due to: the plant coming into contact with live conductors plant being too close to high tension power lines overload of electrical circuits damaged or poorly maintained electrical leads and cables damaged electrical switches water near electrical equipment lack of insulation against water contact shorting thermal radiation electrostatic radiation magnetic interference from workplace affecting electrical components 				
STABILITY	 Can machine tip or roll over due to stability system not extending Stability system failing structurally, mechanically, or retract unintentionally Control valve or interlock failure Setting up on soft ground, unlevel or uneven ground, excessive slope Driving on rough surfaces, over potholes, hitting fixed objects, excessive side loads, operation in excessive climatic conditions e.g. wind Uneven SWL weight distribution in the platform 				
HYDRAULIC FAILURE	 Hydraulic system failure Check valve or relief valve failure Hose or cylinder failure - mechanical or fatigue 				
STRUCTURAL FAILURE	 Structural failure due to fatigue, corrosion, or overloading Pin, cable or linkage failure General overload, lifting excessive load, loading platform/ basket in an unintended way 				
MAINTENANCE	 Can anyone be injured: while carrying out routine, preventative or corrective maintenance explosion due to an ignition source near charging battery adjusting equipment for essential components faulty or seized operating a machine that has been damaged or modified operating a malfunctioning machine if the machines guards/covers are missing 				
TRANSPORT	 Can anyone be injured: due to machine instability while loading/unloading, transporting plant or objects falling from transport truck 				
OCCUPATIONAL HAZARDS	 Plant obstructing other plants at site Unauthorised use by untrained personnel 				
GTD_4003_AB	Page 3 of 8				



 Unintended use of duplicate controls while working
 Hearing loss or communication interference due to excessive noise
 Use of the plant as a crane of lifting device other than MEWP

	Table 1				
Hazard Type Checklist					
OTHER HAZARDS, EJECTION OF PARTS VIBRATION					

Hazard Control Measures

Table 2 provides a summary of potential hazards associated with the plant and the relevant control measures Genie has implemented to minimise those potential hazards to the operator, platform occupants, maintenance personnel and bystanders.

1OCCUPATIONAL HAZARDSa trained, or untrained, operator leads to an accident.and safety manuals supplied with the plant. Use good safe work practices in a commonsense way. Only have trained/certified operators, directed by inform and knowledgeable supervision, running the machine.2WORKSITE HAZARDSFailure to perform a jobsite risk assessmentA complete jobsite risk assessment should be performed prior using the plant. To assist with this effort, Genie provides operators and service manuals which identifies some of the common residual risks for the plant. Every employer, user, ar operator should review these residual risks and implement th necessary control measures to avoid them. Users and employ should also research other supplemental information regarding	Table 2			
NUMBERHAZARD TYPELOCATION/SCENARIOCONTROL MEASURES TO REDUCE RISK1OCCUPATIONAL HAZARDSGeneral operation by a trained, or untrained, operator leads to an accident.• Comply with employer, job site and governmental rules. • Read, understand and follow the instructions in the opera and safety manuals supplied with the plant. • Use good safe work practices in a commonsense way. • Only have trained/certified operators, directed by inform and knowledgeable supervision, running the machine.2WORKSITE HAZARDSFailure to perform a jobsite risk assessmentA complete jobsite risk assessment should be performed prior using the plant. To assist with this effort, Genie provides operator should review these residual risks and implement th necessary control measures to avoid them. Users and employ should also research other supplemental information regarding			Hazard C	Control Measures
1OCCUPATIONAL HAZARDSGeneral operation by a trained, or untrained, operator leads to an accident.Read, understand and follow the instructions in the opera and safety manuals supplied with the plant. Use good safe work practices in a commonsense way.2WORKSITE HAZARDSFailure to perform a jobsite risk assessmentA complete jobsite risk assessment should be performed prior using the plant. To assist with this effort, Genie provides operators and service manuals which identifies some of the common residual risks for the plant. Every employer, user, ar operator should review these residual risks and implement th necessary control measures to avoid them. Users and employ should also research other supplemental information regarding		HAZARD TYPE	LOCATION/SCENARIO	CONTROL MEASURES TO REDUCE RISK
2 WORKSITE HAZARDS Failure to perform a jobsite risk assessment Failure to perform a jobsite risk assessment source manuals which identifies some of the common residual risks for the plant. Every employer, user, ar operator should review these residual risks and implement th necessary control measures to avoid them. Users and employ should also research other supplemental information regarding	1		a trained, or untrained, operator	 Read, understand and follow the instructions in the operators and safety manuals supplied with the plant. Use good safe work practices in a commonsense way. Only have trained/certified operators, directed by informed
	2		jobsite risk	
3 STRUCTURAL FAILURE Failure of any FAILURE structure of any it.e. slope)	3			operating configuration, envelope, and approved conditions



4	STRUCTURAL FAILURE	Failure of any structure	Structural analysis takes into consideration a number of foreseeable forces including gravitational (based on rated capacity), dynamic, wind and manual forces.
5	STRUCTURAL	Failure of any	Structural analysis is verified by physically testing the structural
5	FAILURE	structure	soundness through both static and dynamic loading.
6	STRUCTURAL	Failure of any	All calculations, and verification, meets or exceeds the required
6	FAILURE	structure	structural safety factors of AS1418.10.

			Table 2 Control Measures
HAZARD NUMBER	HAZARD TYPE	LOCATION/SCENARIO	CONTROL MEASURES TO REDUCE RISK
7	STABILITY	Tip-over	All plants have undergone detailed stability analysis. These calculations take into consideration the machines expected operating configuration, envelope, and approved operating conditions (i.e. slope)
8	STABILITY	Tip-over	Stability analysis takes into consideration a number of foreseeable forces including gravitational (based on rated capacity), dynamic, wind and manual forces.
9	STABILITY	Tip-over	Stability analysis not only evaluates the machines static condition, but also potential effects of dynamic conditions (i.e. braking, and depressions)
10	STABILITY	Tip-over	Stability analysis is verified by physically testing the static and dynamic stability of the design.
11	STABILITY	Tip-over	All calculations, and verification, meets or exceeds the required stability safety factors of AS1418.10.
12	STABILITY	Plant drives onto terrain that exceeds allowable limits.	All plants are equipped with a chassis inclination devise which sounds an alarm when the terrain slope is approaching the allowable limits.
13	STABILITY	trying to retract extended outriggers when platform is elevated	Plants equipped with outriggers prevent the platform from being elevated until the outriggers have been fully extended. The design will not allow the retraction of the outriggers until the platform has been completely stowed/lowered.
14	STABILITY, HYDRAULIC FAILURE	Platform elevated and hydraulics fail	Outriggers are protected from unintentionally retracting.
15	STABILITY	Driving too fast for the terrain conditions	When the platform on the plant is elevated, the drive speed is reduced. Proportional drive is provided.
16	STABILITY, COLLISION	Loss of braking while traveling	Brakes on all scissor plants automatically engage when the power to them has stopped or failed. Brakes are capable of holding the plant on approved slopes.
17	STABILITY, COLLISION	Plant does not stop quickly enough	The plants stopping distance at maximum speed meets or exceeds the requirements of AS 1418.10. Control positions on the plant are located and designed to allow excellent visibility and to allow slow, deliberate movements to prevent contact with adjacent objects. The plant can be fitted with secondary guarding for overhead protection based on risk assessment of work in tight overhead areas.
18	OCCUPATIONAL	Unauthorised use	All plants are equipped with a key switch to prevent unauthorised



	HAZARDS		use. Additionally only one control panel can be operated at any
19	CRUSHING, ENTANGLEMENT, CUTTING, SEVERING, STABBING, SHEARING, IMPACT, HIGH TEMPERATURES,	General operation	given time. Guards are provided on the plant to protect persons at control positions, or standing adjacent to the plant at ground level, against thermal or mechanical hazards.
			Table 2 Control Measures
HAZARD NUMBER	HAZARD TYPE	LOCATION/SCENARIO	CONTROL MEASURES TO REDUCE RISK
20	FIRE/EXPLOSION	General maintenance	The filling points for flammable fluids are positioned to minimise the risk of fire from spillage onto hot parts.
21	HIGH TEMPERATURES	General operation	The electric motor is positioned away from control positions and cables are insulated.
22	CHEMICAL BURN, FIRE/EXPLOSION, EJECTION OF PARTS	General operation	The battery, or batteries, are constrained to prevent unintentional displacement, or ejection of electrolyte, even in an overturning event.
23	FIRE/EXPLOSION	General operation	Each battery is positioned and designed such that dangerous accumulations of gases do not occur in places occupied by operators.
24	STABILITY, STRUCTURAL FAILURE	Overloading platform	The plant is equipped with a load-sensing system which protects the plant and operator from reaching a point where the platform can be operated when the platform has been overloaded.
25	STABILITY, STRUCTURAL FAILURE	Tip-over	To help avoid overturning of the plant the structure for the plant is equipped with non-mechanical limiting devices (i.e. limit switches) to limit the operation.
26	TRAPPING, CUTTING, SEVERING, SHEARING	General operation	Trapping and shearing points between moving parts which are within reach of persons on the work platform or standing adjacent to the plant at ground level are avoided by providing safe clearances in accordance with AS 4024.1801, AS 1802 or AS 1803 or guarding in accordance with AS 4024.1601 as applicable.
27	MAINTENANCE, CRUSHING, SEVERING, SHEARING	General maintenance	When the work platform of a plant needs to be raised for routine servicing purposes, the hydraulic system allows the extending structure to be held in the required position. A scissor stack mechanical safety arm is provided to hold the structure in a fixed position.
28	STABILITY, COLLISION	Plant moves to quickly when platform is elevated	The drive speed of the plant are reduced and restricted, once the platform is elevated, in accordance with AS1418.10
29	COLLISION	Unintended platform movement	The plant extending drive system is designed and constructed to prevent any inadvertent movements of the extending structure.
30	HYDRAULIC FAILURE	Overloading the structure and drive system.	Pressure limiting devices are provided to protect the extending structure, and drive system, to prevent structural damage.

GTD_4003_AB



31 FAILURE movement or fails, this system automatically locks the work platforms movements, in any position.		31	HYDRAULIC FAILURE	Unintended platform movement	
--------------------------------------------------------------------------------------------------------------	--	----	----------------------	---------------------------------	--



Product Safety

The information provided in this document is only a small example of the activities which have been undertaken by Genie Industries to ensure the safety of the plants. These include:

- Performing computer simulation/modeling of product and internal design calculations.
- Independent design review by an independent engineer to local design requirements is completed in Australia.
- Cycle testing of components to ensure fatigue life is adequate for a 10 year life is completed.
- Extensive field testing of prototype units to ensure faults and hazards are identified before design is finalised.
- Conducting an extensive Product Development Process, on each plant design, which incorporates risk assessment and field testing to prove the plant design is safe to use, by a trained and authorized operator, for its intended purpose.

Occupational Health & Safety Legislation

The below legislation has been used to produce this document.

ACT, NSW, QLD:	Work Health and Safety Act 2011
NT:	Work Health and Safety (National Uniform Legislation) Act 2011
SA, TAS:	Work Health and Safety Act 2012
VIC:	Occupational Health and Safety Act 2004
WA:	Occupational Safety and Health Act 1984